



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

AUG 10 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/10/2015 Operator COPC API #30-0 45-05726

Property Name Bug Dos Pal Well No. 1 Location: Unit M Section 19 Township 26 Range 8

Well Status(~~Shut-In~~ or Producing) Initial PSI: Tubing 5 Intermediate 0 Casing 11 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0	0	11		
10 min	0	0	11		
15 min	0	0	11		
20 min	0	0	12		
25 min	0	0	12		
30 min	0	0	12		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow ☒	
Surges ☐	
Down to Nothing ☐	
Nothing ☐	
Gas ☐	
Gas & Water ☐	
Water ☒	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 6.6

INTERMEDIATE —

REMARKS:

Bradenhead flowed about a pint of water when opened and flowed about 3 gal in 30 min. test. Intermediate full of cement. Requested water sample.

By Donnell Patten
MSO
(Position)

Witness Paul Wiike
36.4694748
107.7282791

E-mail address: _____