



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 13 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 13-AUG-2015 Operator BURLINGON API #30-0 48-27456

Property Name KAH DES PAH Well No. 2 Location: Unit 5 Section 18 Township 26 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 130 Intermediate N/A Casing 141 Bradenhead 141

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min			142		
10 min			142		
15 min			142		
20 min			143		
25 min			143		
30 min			144		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 138 INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND IT HAD A STRONG
GAS FLOW FOR THE FIRST 5 SECONDS AND THEN A STEADY
LIGHT FLOW FOR THE REST OF THE TEST. REQUESTED A GAS ANALYSIS

By Denny Trujillo
MSO
(Position)

Witness John Burdon

E-mail address _____