1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Avenue, Artesia, NM 88210

District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

For drilling and production facilities, submit to appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe office

Form C-144

June 1, 2004

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes V No

(WFS CLOSURE) Type of action: Registration of a pit or below	v-grade tank Closure of a pit or below-grade tank	~						
Operator: CONOCOPHILLIPS COMPANY Telephone:	e-mail address:							
Address: PO BOX 2197 HOUSTON, TX 77252								
Facility or well name: SAN JUAN 29 6 UNIT #090 API #: 30-039-		<u>15</u> T <u>29N</u> R <u>6W</u>						
County: RIO ARRIBA Latitude 36.727	791 Longitude -107.44684	NAD: 1927 🗹 1983 🗌						
Surface Owner: Federal 🗹 State 🗌 Private 🔲 Indian 🗍	-							
<u>Pit</u>	Below-grade tank							
Type: Drilling Production Disposal	Volume: bbl Type of fluid:							
Workover	Construction Material: Double-walled, with leak detection? Yes If not, explain why not.							
Lined Unlined 🗹	Duulic-wailed, with loak delection. 1 vo	Jiam wity not.						
Liner Type: Synthetic 🖾 Thickness mil Clay 🏢								
Pit Volume 77 bbl								
Depth to ground water (vertical distance from bottom of pit to seasonal high	Less than 50 feet	(20 points)						
water elevation of ground water.)	50 feet or more, but less than 100 feet	(10 points) 0						
	100 feet or more	(0 points)						
Wellhead protection area: (Less than 200 feet from a private domestic water	Yes	(20 points)						
source, or less than 1000 feet from all other water sources.)	No	(0 points) $\underline{0}$						
Distance to surface water: (Horizontal distance to all wetlands, playas,	Less than 200 feet	(20 points)						
irrigation canals, ditches, and perennial and ephemeral watercourses.)	200 feet to 1,000 feet Greater than 1,000 feet	(10 points) <u>0</u> (0 points)						
	Greater than 1,000 feet	(0 points)						
	Ranking Score (TOTAL POINTS):	<u>0</u>						
	ationship to other equipment and tanks. (2) Indicate disposal	· ·						
onsite box if your are burying in place) onsite offsite offsite, name of facility action taken including remediation start date and end date. (4)Groundwater encountered: No V Yes I If yes, show depth below ground surface ft.								
8910/13								
Additional Comments: Meter: 86540								
	m on reco 2000 of							
CONS ON THE RESERVED ON THE RE								
C CONS ON.								
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further earlies the above-described pit or below-grade								
tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan								
Date: 9/27/05 Mr 2 For wers								
Printed Name/Title Mark Harvey for Williams Field Services Signature								
Your certification and NMOCD approval of this application/closure does not relieve the operator of liablility should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or								
regulations.								
Approval:		— OCT 12 200						
Printed Name/Title Signa Signa	ature Deny feerif	Date:						

ADDENDUM TO OCD FORM C-144


Operator: CONOCOPHILLIPS COMPANY

Well Name: SAN JUAN 29 6 UNIT #090


API 30-039-07622

Meter: 86540

Facility Diagram:



Sampling Diagram:



Pit Dimensions

Length 12 Ft.

Width 12 Ft.

Depth 3 Ft. **Location of Pit Center**

Latitude 36.72779

Longitude -107.4464

(NAD 1927)

Pit ID

865401

Pit Type

Glycol Dehydrator

Date Closure Started: 4/24/03

Closure Method:

Pushed In

Date Closure Completed: $\frac{4/24/03}{}$

Bedrock Encountered?

Cubic Yards Excavated:

Vertical Extent of Equipment Reached?

Description Of Closure Action:

The pit was assessed and sampled in accordance with NMOCD guidelines. Based on assessment findings, the pit was backfilled.

Pit Closure Sampling:

Sample ID

Sample Date

Head

BTEX Space Total

Benzene (mg/kg) TPH DRO

Purpose

Location

Depth

104725JUN02 6/25/02 1800 ASSESS

(mg/kg)

(mg/kg)



Pace Analytical Services, Inc.

9608 Loiret Blvd. Lenexa, KS 66219

Phone: 913.599.5665 Fax: 913.599.1759

Lab Project Number: 6060215

Client Project ID: N.M. Pits Assessments

Solid results are reported on a dry weight basis

605229012 Lab Sample No: Project Sample Number: 6060215-001 Date Collected: 06/25/02 10:47

Client Sample ID: 1047253UN02 Matrix. Soil

Date Received: 06/27/02 09:20

Client Sample ID: 104725JUN02			Matrix: Soil			Date Received: 06/27/02	
Parameters	Results	Units	Report Limit	Analyzed	Ву	CAS No.	Qual RegLmt
GC Semivolatiles							
Total Extractable Hydrocarbons	Prep/Method:	OA2 / OA2					
Mineral Spirits	ND	mg/kg	11.	07/04/02 02:23	WAW		
Jet Fuel	ND	mg/kg	11.	07/04/02 02:23	WAW		
Kerosene	ND	mg/kg	11.	07/04/02 02:23	WAW		
Diesel Fuel	1800	mg/kg	11.	07/04/02 02:23	WAW	68334-30-5	
Fuel 0il	ND	mg/kg	11.	07/04/02 02:23	WAW	68334-30-5	
Motor 0il	ND	mg/kg	11.	07/04/02 02:23	WAW		
n-Tetracosane (S)	117	%		07/04/02 02:23	WAW	646-31-1	
p-Terphenyl (S)	99	%		07/04/02 02:23	WAW	92-94-4	
Date Extracted				07/02/02			
Organics Prep							
Percent Moisture	Method:						
Percent Moisture	12.4	*		07/04/02	MIM		
GC Volatiles							
TPH Gas/BTEX	Prep/Method:	TPH GRO/BT	EX / EPA 8021/	0A1			
Gasoline Range Hydrocarbons	9000	ug/kg	5700	07/02/02 18:02	SHF		
Benzene	ND	ug/kg	57.	07/02/02 18:02	SHF	71-43-2	
Toluene	ND	ug/kg	57.	07/02/02 18:02	SHF	108-88-3	
Ethylbenzene	ND	ug/kg	57.	07/02/02 18:02	SHF	100-41-4	
Xylene (Total)	ND	ug/kg	150	07/02/02 18:02	SHF	1330-20-7	
a,a,a-Trifluorotoluene (S)	104	%		07/02/02 18:02	SHF	98-08-8	
4-Bromofluorobenzene (S)	96	%		07/02/02 18:02	SHF	460-00-4	

Date: 07/05/02

Page: 1

REPORT OF LABORATORY ANALYSIS