



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/21/15 Operator COPC API #30-0 45-05660

Property Name Whan Jones Well No. #1 Location: Unit K Section 30 Township 26 Range 8

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 31 Intermediate 11 Casing 38 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	11	40	0	40
10 min	0	11	40	0	41
15 min	0	11	40	0	41
20 min	0	11	40		
25 min	0	11	40		
30 min	0	11	40		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow ☒	☒
Surges ☐	☐
Down to Nothing ☐	☐
Nothing ☐	☐
Gas ☐	☐
Gas & Water ☐	☐
Water ☒	☐

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 6 INTERMEDIATE 1

REMARKS:

Bradenhead had a trickle of water for full 30 min.
Intermediate Just a Puff. water sample requested

By Donall J. Pugh

(Position)

Witness Paul Wiebe

36.455724
-107.7258453

E-mail address _____