



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 25 2015

Date of Test 25-AUG-2015 Operator MARALEV API # 30-025 32944
Property Name PINON 35 Well No. 44 Location: Unit _____ Section 35 Township 25 Range 1
Well Status (Shut-In or Producing) Initial PSI: Tubing 80 Intermediate N/A Casing 44 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min			44		
10 min			44		
15 min			44		
20 min			44		
25 min			44		
30 min			44		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By Bob Spencer
PUMPER
(Position)

Witness John Dugan

E-mail address _____