



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3distrct.htm](http://emnr.state.nm.us/ocd/District%20III3distrct.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/28/2015 Operator Concepcion Phillips API # 30-045-20258
Property Name Fluance Well No. 1 Location: Unit E Section 26 Township 28 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 78 Intermediate 0 Casing 175 Bradenhead 28

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
5 min	<u>25</u>	<u>0</u>	<u>175</u>	<u>0</u>	<u>171</u>
10 min	<u>25</u>	<u>0</u>	<u>175</u>	<u>0</u>	<u>171</u>
15 min	<u>24</u>	<u>0</u>	<u>174</u>	<u>0</u>	<u>171</u>
20 min	<u>24</u>	<u>0</u>	<u>174</u>		
25 min	<u>24</u>	<u>0</u>	<u>174</u>		
30 min	<u>23</u>	<u>0</u>	<u>172</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	<u>X</u>

OIL CONS. DIV DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

AUG 28 2015

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 25 INTERMEDIATE 0

REMARKS:

BH plumbed to portable tank through 2" line, slight leak on casing quick connect caused pressure drop during test, water flowed throughout test, clear with light HC odor. Int. through 1" fittings, light puff then vapor for 1 min then nothing. request water sample.

By Jennifer D Birdsey
MSO
(Position)

Witness Jonathan R. Kelly

E-mail address _____