



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8-14-2015 Operator Western Minerals & Oil API # 45-21316

Property Name Marron Well No. 5 Location: Unit H Section 27 Township 27N Range 8W

Well Status (Shut-In or Producing) Tubing 26 Intermediate --- Casing 44 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>---</u>	<u>44</u>	Steady Flow	
10 minutes	<u>0</u>	<u>---</u>	<u>45</u>	Surges	
15 minutes	<u>0</u>	<u>---</u>	<u>44</u>	Down to Nothing <u>X</u>	
20 minutes	<u>0</u>	<u>---</u>	<u>44</u>	Nothing	
25 minutes	<u>0</u>	<u>---</u>	<u>45</u>	Gas	
30 minutes	<u>0</u>	<u>---</u>	<u>44</u>	Gas & Water	
				Water	<u>✓</u>

If bradenhead flowed water, check all of the descriptions that apply below:

OIL CONS. DIV DIST. 3

CLEAR --- FRESH --- SALTY --- SULFUR --- BLACK ---

SEP 03 2015

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE ---

REMARKS: Bradenhead hpd 4 PSI on it, but
blew down to nothing in 10 seconds

By Bob Chenault
Pumper
(Position)

Witness Steven Gallegos

E-mail address bob@ccnm.com