



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnd.state.nm.us/ocd/District III/3ddistrict.htm](http://emrnd.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-14-2015 Operator Western Minerals & Oil API # 45-06248

Property Name Marron Well No. 2 Location: Unit H Section 27 Township 27N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate -- Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>22</u>		
10 min	<u>0</u>	<u>—</u>	<u>22</u>		
15 min	<u>0</u>	<u>—</u>	<u>21</u>		
20 min	<u>0</u>	<u>—</u>	<u>21</u>		
25 min	<u>0</u>	<u>—</u>	<u>22</u>		
30 min	<u>0</u>	<u>—</u>	<u>22</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE —

REMARKS:

Had a PSI but blew down to
nothing in three seconds

By Bob Chenault

Witness Steven Gallegos

Pumper

(Position)

E-mail address Bob@ccinm.com