RECEIVED

MAY 27 2015

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137

BUREAU OF LAND MANAGEMENT					Expires: March 31, 2007
BUREAU OF LAND MANAGEMENT Farmington Field Office Bureau of Land Manager				5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS				MMMM	110324
Do not use this form for proposals to drill or to re-enter an				6. If Indi	ian, Allottee or Tribe Name
abandoned well. Use Form 3160-3 (APD) for such proposals.					
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Uni	t of CA/Agreement, Name and/or No.
1. Type of Well					
				8. Well Name and No. Chaco 2308-24I #155H	
Oil Well Gas Well Other 2. Name of Operator				9. API Well No.	
WPX Energy Production, LLC				30-045-35551	
3a. Address		3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area	
PO Box 640 Aztec, NM 87410		505-333-1816		Basin Mancos (660')	
4. Location of Well <i>(Footage, Sec., T.,R.,M., or Survey Descrip</i> SHL: 1524' FSL & 255' FEL SEC 24 T23N R8W BHL: 2400' FSL & 246' FWL SEC 24 T23N R8W		otion)		11. Country or Parish, State San Juan, NM	
12. CHECK T	HE APPROPRIATE BOX(ES) TO INDICATE NATU	RE OF NOTICE, R	EPORT O	R OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent			Produ	ection	
	Acidize	Deepen	(Start/Resu		Water Shut-Off
	Alter Casing	Fracture Treat	Recla	mation Well Integrity	
	Casing Repair	New Construction	Recor	nplete	Other
Subsequent Report	Cusing Ropun	rew construction			COMPLETION
Q.	Change Plans	Plug and Abandon	Temp Abandon	orarily	
Final Abandonment Notice	Convert to Injection	Plug Back		Disposal	-
Bond under which the work will be of the involved operations. If the op Final Abandonment Notices must b inspection. 4/24/15- MIRU HWS #17. NU B Run seal assembly on 4 ½", 11.6 casing, casing pup jt, casing han	or recomplete horizontally, give performed or provide the Bond heration results in a multiple cone is filed only after all requirements. OP. 5#, P-110 casing, seal assuger, total casing landed	subsurface locations and measu No. on file with BLM/BIA. Re- apletion or recompletion in a ne ts, including reclamation, have embly w/ NO-GO, w/ 38, 5582'. Landed w/ 36,000	ared and true vertical d quired subsequent repo w interval, a Form 316 been completed and th jts of 4 ½" casing, b# on liner hanger	epths of all jorts must be 50-4 must be e operator harmarker jorts, 18,000 o	pertinent markers and zones. Attach the filed within 30 days following completion filed once testing has been completed. as determined that the site is ready for final ts3915-3935, 100jts of 4 ½" on casing hanger. Pressure tested
4 ½" casing to 1500psi. Charted record tested for 30 minutes – Test was good. Pressure tested 7" intermediate casing to 1500psi, charted record test for 30 minutes – test was good. Shut in 7" w/ 1500psi.					
record test for 50 minutes – tes	t was good. Shut iii / w	/ 1300b2l.			
4/27/15- C/O to 10288'					110 P11 P1 1 P
					IDENTAL
4/28/15- Nipple down BOP. RD HWS #17. Nipple up Frac valve.					PHILAB
<u>5/8/15</u> - Perf Gallup 1 st stage, 1	0103'-10228' + RSI TOOI	_ @10291' with 18, 0.40'	' holes.		
5/9/15-5/10/15 prepare for fra	С				
14. I hereby certify that the foregoing					
Name (Printed/Typed) Marie E. Jaramillo Title Permit Tec				.l.	
Marie E. Jaramillo Title Permit Tech					
Signature Date 5115					
V V	THIS SPACE FO	R FEDERAL OR S		USE	
Approved by			Title		Data
Conditions of approval if any are atta	ched Approval of this notice	does not warrant or certify the	Title		Date
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					ACCEPTED FOR DECOR

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Chaco 2308-24I #155H

5/11/15 - Frac Mancos 1st stage 10103'-10291' - with 215,357# 20/40 PSA Sand

Set flo-thru frac plug @ 10070' MD. Perf 2nd 9802'-10003'- with 24 total, 0.40" holes. Frac Mancos 2nd stage with 216,800# 20/40 PSA Sand Set flo-thru frac plug @ 9740' MD. Perf 3rd stage 9486'- 9702'- with 24, 0.40" holes. Frac Mancos 3rd stage with 215,700#, 20/40 PSA Sand

5/12/15-Set flo-thru frac plug @ 9450' MD. Perf 4th stage 9185'-9383'- with 24, 0.40" holes. Frac Mancos 4th stage with 220,740# 20/40 PSA Sand

Set flo-thru frac plug @ 9135' MD. Perf 5th stage 8882'-9085'-with 24, 0.40" holes. Frac Mancos 5th stage with 216,552#, 20/40 PSA Sand

RIH w/WL to 2,850' while getting ready to start WL to pump down, a Baker Hughes Employee opened the wrong N2 ground valve and opened up to the 155H. Started Pumping Nitrogen down w/WL and causing wireline to exceed maximum speed, pre-setting the plug at 2,904' and causing WL to get stuck in the Wellbore.

5/13/15- MIRU HW #10

DO CBP @ 2904' & Chased to bottom of the top of plug #5 @ 9135'

5/14/15- RDMO with HW #10. MIRU Baker Hughes / W/L. Continue ahead w/ Frac.

Set flo-thru frac plug @ 8855' MD. Perf 6th stage 8583'-8784'- with 24, 0.40" holes. Frac Mancos 6th stage with 214,732#, 20/40 PSA Sand Set flo-thru frac plug @ 8530' MD. Perf 7th stage 8282'-8483'- with 24, 0.40" holes. Frac Mancos 7th stage with 216,434#, 20/40 PSA Sand

<u>5/15/15</u>-Set flo-thru frac plug @ 8250' MD. Perf 8th stage 7981'-8182'- with 24, 0.40" holes. Frac Mancos 8th stage with 213,237#, 20/40 PSA Sand

Set flo-thru frac plug @ 7930′ MD. Perf 9th stage 7680′-7881′- with 24, 0.40″ holes. Frac Mancos 9th stage with 208,192#, 20/40 PSA Sand Set flo-thru frac plug @ 7650′ MD. Perf 10th stage 7379′-7580′- with 24, 0.40″ holes. Frac Mancos 10th stage with 219,692#, 20/40 PSA Sand Set flo-thru frac plug @ 7330′ MD. Perf 11th stage 7072′-7279′- with 24, 0.40″ holes. Frac Mancos 11th stage with 272,135#, 20/40 PSA Sand Set flo-thru frac plug @ 7020′ MD. Perf 12th stage 6762′-6978′- with 24, 0.40″ holes. Frac Mancos 12th stage with 275,460# 20/40 PSA Sand Set flo-thru frac plug @ 6690′ MD. Perf 13th stage 6446′-6659′- with 24, 0.40″ holes. Frac Mancos 13th stage with 258,840#, 20/40 PSA Sand Set flo-thru frac plug @ 6380′ MD. Perf 14th stage 6115′-6341′- with 24, 0.40″ holes.

5/16/15 - Frac Mancos 14th stage with 272,240#, 20/40 PSA Sand

Set flo-thru frac plug @ 6085' MD. Perf 15th stage 5784'-6015'- with 24, 0.40" holes. Frac Mancos 15th stage with 259,440#, 20/40 PSA Sand

Set 4-1/2" CIPB @ 4990'. RDMO Frac & WL.

5/17/15 - MIRU HWS #10

NU BOP pressure test - good test. DO CIBP @ 4990'.

<u>5/18/15</u>-DO flo- thru Frac plug @ 6085′-, 6380′, 6690′, 7020′, 7330′, 7650′, 7930′, 8250′, 8530′, 8855′, 9135′, 9450′, 9740′ and 10070′ C/O well to 10288′

5/19/15 - Pulled and lay down tieback string.

Landed well @ 5507' w/ 14.5' KB as follows, ½ MS, 1 jt of 2.875" J-55tbg, 2.25" RN set at 5476', 2jts of 2.875" J-55 tbg, **7" AS1-X Pkr st at** 5413' w/ 12K in Tension, on/off tool, 4' pup jt, 1jt 2.875" J-55 tbg, GLV#1 set at 5369', 5jts of 2.875" J-55 tbg, 2.31" XN set at 5211', 13jts of 2.875" J-55 tbg, GLV#2 st at 4811', 15jts of 2.875" J-55 tbg, GLV#3 set at 4346', 15jts of 2.875" J-55 tbg, GLV #4 set at 3881', 14jts of 2.875" J-55 tbg, GLV #5 set at 3446', 15jts of 2.875" J-55 tbg, GLV #6 set at 2981', 16jts of 2.875" J-55tbg, GLV #7 set at 2485', 18jts of 2.875" J-55, GLV #8 set at 1928', 25jts of 2.875" J-55tbg, GLV #9 set at 1155', 37jts of 2.875" J-55 tbg. Total 177jts of 2.875" J-55 tbg in well. Locked down tbg hanger. RD and LD handling tools. RD rig floor.

NOTE: Delivery and flowback test information will be reported on delivery sundry.