



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District III/3dlatric.htm](http://emrmd.state.nm.us/ocd/District%20III/3dlatric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

SEP 21 2015

Date of Test 4-15-2015 Operator BMD API #30-0 45-05680

Property Name Foster Riddle Well No. 2 Location: Unit Section 25 Township 26N Range 09W

Well Status (Shut-In or Producing) Initial PSI: Tubing 139 Intermediate Casing 138 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>138</u>		
10 min	<u>0</u>		<u>138</u>		
15 min	<u>0</u>		<u>138</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>NO</u>	
Surges	<u>NO</u>	
Down to Nothing	<u>Yes</u>	
Nothing	<u>Yes</u>	
Gas	<u>NO</u>	
Gas & Water	<u>NO</u>	
Water	<u>NO</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 PSI INTERMEDIATE

REMARKS: Bradenhead had 3 PSI It blowed down to 0 PSI
in 30 seconds and stayed at 0 PSI for duration
of Test

By Chip Suskey

Witness

Lease operator
(Position)

E-mail address csuskey@bmgdrilling.com