

"A graceful, alert, swift moving little drilling company"

30-045-29772

September 30, 2005

Mr. Paul Thompson Walsh Engineering 7415 East Main Farmington, NM 87402-5358

Re:


Deviation Survey

Toe #2

Below is the deviation survey for the Toe #2 well located in San Juan County, New Mexico:

1/2° @ 120' 1/2° @ 630'

3/4° @ 1300'



CHIHUAHUA DRILLING, LLC SAN JUAN OIL & GAS, INC., Member

Patti L. Davis,

ACKNOWLEDGMENT

State of Colorado

§ §

County of Arapahoe

The foregoing instrument was acknowledged before me by Patti L. Davis, as Vice President of San Juan Oil & Gas, Inc., Member of Chihuahua Drilling, LCC this 30th day of September, 2005.

LARISA BARAYEVA **NOTARY PUBLIC** STATE OF COLORADO

My Commission Expires 06/

Notary Public