Submit 3 Copies To Appropriate District Office District I	Energy Minerals and Netural Decourage		Form C-103 May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210				30-045-06019	
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease Federal STATE FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505		Federal SF-08110	1		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Chartier		
1. Type of Well: Oil Well Gas Well Other			8. Well Number	1	
2. Name of Operator			9. OGRID Number 014634		
Merrion Oil & Gas			10 P 1 W/11		
3. Address of Operator 610 Reilly Ave, Farmington, NM 87401			10. Pool name or Wildcat Gallegos Gallup		
4. Well Location			Gunegos Gunup		
Unit Letter M : 790 feet from the south line and 790 feet from the west line					
Section 4	Township 26N	Range 12W	NMPM Coun		
	11. Elevation (Show whether DR			.,	
	5971' GR				
Pit or Below-grade Tank Application or Closure					
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material					
12. Check Ap	propriate Box to Indicate N	lature of Notice,	Report or Other	Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON					
OTHER: Abandon WAW PC/ complete Basin Fruitland 🛛 OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
Merrion Oil & Gas mistakenly listed this pit on its earthen pit inventory. There was a fiberglass pit in an excavation, but the sides were visible, so it should not have been classified as an earthen pit. The fiberglass pit was removed, and the excavation was filled w/ clean soil. We estimate this work was done sometime in September 2004.					
19 20 21 22 33 33 33 33 33 33 33 33 33 33 33 33					
DEC 200 %					
DEC 2005 RECEIVED OIL CONS. DRV. DIST. 3					
OL CONS. DIV.					
ST. 3 S					
	1	KO .			
		* \$ \ 9 C	7 E 60°		
			A A A A A A A A A A A A A A A A A A A		
I hereby certify that the information ab grade tank has been/will be constructed or clo	ove is true and complete to the b sed according to NMOCD guidelines	est of my knowledg □, a general permit □	ge and belief. I furthed or an (attached) altern	er certify that any pit or belowative OCD-approved plan □.	
SIGNATURE	TITLE	Production Engi	ineerl	DATE12/19/05	
Type or print name Connie Dinning	E-mail address: cdinning@	merrion hz	Telephone No. 505	5 324 5326	
For State Use Only	~ with voo. Cumming(-,		·	
APPROVED BY I TO M		UTY OR & GAS INS	pector, dest. 🍻	DEC 21 2005	
APPROVED BY: Conditions of Approval (if any):	TITLE_		· · ·	_DATE	
Conditions of Approvia (II dily).		r	, **		