



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11/10/2015 Operator Burlington API #30-0 39-2015
Property Name San Juan 274 Unit Well No. 38 Location: Unit L Section 6 Township 27 Range 4
Well Status (Shut-In) or Producing) Initial PSI: Tubing 252 Intermediate 1.4 Casing 252 Bradenhead 0.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1.4	252	0.0	252
10 min	0	1.4	252	0	252
15 min	0	1.4	252	0	252
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV DIST. 3

NOV 10 2015

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH through 1/2" needle valve, Intermediate through 1" valve, light blow to whisper in 1 min 15 sec to vapor by 2 min, to nothing by 5 min. Light vapor, no pressure. Request gas analysis on Intermediate and Casing string.

By Kevin Peterson COPC

Witness Jonathan D. Kelly

(Position)

E-mail address _____