



30-045-09482

864 20 Road, Unit A
Fruita, Colorado 81521
(970) 858-8550
FAX (970) 858-8155

P.O. Box 338
Ignacio, Colorado 81137
(970) 563-4000
FAX (970) 563-4116

OIL CONS. DIV DIST. 3
MAY 27 2014

May 20, 2014


State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410

Re: 2014 District III Bradenhead Tests

Attn: Monica Kuehling

Attached are the bradenhead tests that were conducted on our required wells. A water sample has been submitted on our **Scott #1 and a remedial plan for repairs will be submitted** to the NMOCD. Please call me if you have any questions. Our office number is (970) 563-4000

Sincerely,


Dennis R. Reimers
Engineering Manager

Attachment



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-23-14 Operator Maralex Resources API #30-0 45-0948Z
Property Name Scott Well No. #1 Location: Unit Section 18 Township 30N Range 11W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0[#] Intermediate N/A Casing 4[#] Bradenhead 10^{1/2}[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	10 ^{1/2} [#]	N/A	4 [#]	N/A	N/A
10 min	10 ^{1/2} [#]		4 [#]		
15 min	10 [#]		4 [#]		
20 min	10 [#]		4 [#]		
25 min	10 [#]		4 [#]		
30 min	10 [#]		4 [#]		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<input checked="" type="checkbox"/>	N/A
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	<input checked="" type="checkbox"/>	

OIL CONS. DIV DIST. 3
MAY 27 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 10[#] INTERMEDIATE N/A

REMARKS:

A water sample is being analyzed & will be submitted w/ a Remedial plan for repairing this well.

By Douglas Jarama
Pumper
(Position)

Witness _____

E-mail address _____