



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DEC 18 2015

Date of Test 10/14/15 Operator ENERVEST OPERATING API #30-0 45326050000

Property Name CANDADO Well No. 1 Location: Unit M Section 15 Township 26N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 50 Intermediate N/A Casing 95 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>2</u>	<u>N/A</u>	<u>95</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>95</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>95</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 2 INTERMEDIATE N/A

REMARKS:

opened bradenhead / 2 psi blew down to nothing -

By Schoultz

Witness _____

operator
(Position)

E-mail address Schoultz@enervest.net