



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

DEC 18 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12/1/15 Operator BP API #30-0 4521148

Property Name Fluorance C15 Well No. 15 Location: Unit H Section 19 Township 28 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 146 Intermediate - Casing - Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		146		
10 min	0		146		
15 min	0		146		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Blew from 1" valve Slim hole well. Used tubing in place
of casing. BH had no flow.

By [Signature]

Witness _____

(Position)

E-mail address _____