

JAN 14 2016

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnr.state.nm.us/ocd/DistrictIII/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

*STANOLIND*  
~~RECEIVED~~

Date of Test 42233 Operator Elk San Juan API #30-0 45-10667  
Property Name Ute Indian A Well No. 10 Location: Uni M Section 15 Township 31N 15W 31N  
Pressure (Shut-In or Producing) Producing Tubing 16 Intermediate NA Casing 42 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE	
	BH	INT	CSG	INT	CSG
5 minutes	0		42		
10 minutes	0		42		
15 minutes	0		42		
20 minutes	0		42		
25 minutes	0		42		
30 minutes	0		42		

BRADENHEAD INTERMEDIATE

FLOWED FLOWED

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

Nothing

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN \_\_\_\_\_ BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

No pressure on BH. Casing stayed the say same throughout testing.

By Theo Hampton Witness Theo Hampton

(Position)