



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-16-15 Operator Chevron U.S.A. API #30-0 45-31110
Property Name USA 23 Well No. 1 Location: Unit Section 23 Township 32 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 50.2 Intermediate N/A Casing 9.8 Bradenhead 0.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>-</u>	<u>11.3</u>		
10 min	<u>0</u>	<u>-</u>	<u>11.1</u>		
15 min	<u>0</u>	<u>-</u>	<u>11.3</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Initial bradenhead was a puff to nothing.

By Lucinda Padilla
Calder Services.
(Position)

Witness

E-mail address lucinda.p@calderservices.com

OIL CONS. DIV DIST. 3

DEC 28 2015