



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-18-16 Operator M.R. Schalk API #30-0 45-25311
Property Name Charles Hosh Well No. 1E Location: Unit 12 Section 12 Township 27 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 135 Intermediate N/A Casing 145 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>138</u>		
10 min	<u>0</u>		<u>138</u>		
15 min	<u>0</u>		<u>138</u>		
20 min	<u>0</u>		<u>138</u>		
25 min	<u>0</u>		<u>138</u>		
30 min	<u>0</u>		<u>138</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
MAR 18 2016

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Hard blow to light at 10 seconds. flames at
1 minute - clear at 5 min. long puff after 5 min shut in
Valve was loose reason for drop.

By Sgt R

Witness

Monica Kuehling
Re-test in one year

Field Tech

(Position)

E-mail address _____