



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-13 Operator Zulington, Les API #30-0 45-29809
Property Name Allison LH Well No. 60M Location: Unit 16 Section 16 Township 32 Range 6
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 236 Intermediate 1 Casing 253 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>	<u>.9</u>	<u>248</u>	<u>0</u>	<u>198</u>
10 min	<u>0</u>	<u>.8</u>	<u>229</u>	<u>0</u>	<u>195</u>
15 min	<u>0</u>	<u>.8</u>	<u>227</u>	<u>0</u>	<u>192</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>DIST. 3</u>
Gas	<u>OIL CONS. DIV.</u>
Gas & Water	
Water	<u>RCVD MAY 9 '13</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - nothing when opened.

Int - nothing when opened.

Started producing when starting cut. test.

By

Witness Monica Culberson

(Position)

E-mail address