



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-13 Operator Burlington API #30-0 45-31839
Property Name All:sm 44 Well No. 1145 Location: Unit 19 Section 19 Township 32 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 3 Intermediate N/A Casing 8 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		7		
10 min	0		7		
15 min	0		7		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	DIST. 3
Down to Nothing	✓
Nothing	OIL CONS. DIV.
Gas	✓
Gas & Water	RCVD MAY 9 '13
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

dead at 8 seconds

By Rafael Beldardo
MSD
(Position)

Witness Monica Kuehling

E-mail address _____