



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/oed/District III/3distric.htm](http://emnrd.state.nm.us/oed/District%20III/3distric.htm)

MAR 17 2016

(submit 1 copy to above address)

Date of Test 3-17-16 Operator Anderson D. I API #30-0 45-23620
Property Name Federal Well No. 3 Location: Unit Section 30 Township 31 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 69 Intermediate Casing 70 Bradenhead 67

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE					
Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		70		
10 min	0		70		
15 min	0		69		
20 min	0		68		
25 min	0		65		
30 min	0		62		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 7

INTERMEDIATE

REMARKS:

REMARKS: Hard blow to light blow at 37 sec on ch.

Well is Short in-taking problems

By Kelly T. Miller
Production Foreman
(Position)

Witness

Witness Mona Cukling

Request well be schematic
gas analysis from blackhead
and production casing

E-mail address _____