NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

OIL CONS. DIV DIST. 3

APR 12 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-12-16 Operator Burlington Res API #30-0 39-25979

Property Name Johnston A Com C Well No. 9A Location: Unit ___ Section 36 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 121 Intermediate 0 Casing 121 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	0	122	0	124
10 min	0	0	123	0	124
15 min	0	0	123	0	125
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH- clean after Dubb when opened. Nothing when opened after 5 min shut-in. Int. clean at 3 seconds. Nothing when opened after 5 min shut-in

By Wade Stuck Witness Monica Kuehling

(Position)

E-mail address _____