



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 11 2016

Date of Test 11 APR 2016 Operator BRADEN API #30-0 39-30S04

Property Name NEBU Well No. 22M Location: Unit 0 Section 34 Township 31 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 45 Intermediate 0 Casing 52 Bradenhead 6.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	↑	0	52	↑	52
10 min	↑	0	52	↑	52
15 min	↑	0	52	↑	52
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW DOWN TO
NOTHING IN 13 SECONDS. OPENED THE INTERMEDIATE AND
NOTHING CAME OUT

By Daniel Tule

Witness John Durham

(Position)

E-mail address _____