



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 20 2016

Date of Test 04-20-2016 Operator Redwolf Production API #30-0 45-05363

Property Name Payne Well No. 3X Location: Unit I Section 14 Township 25 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 64 Intermediate NA Casing 64 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	Ø	NA	64		
10 min	Ø	↓	64		
15 min	Ø	↓	64		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE _____

REMARKS:

Well is active. Nothing on BH when opened.

By Bruce P. W. Whitworth

Witness [Signature] nmoco

(Position)

E-mail address _____