NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

APR 22 2016

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-22-16 Operator Chevron MCLP API #30-0 45-24392

Property Name Cardon Com SWD Well No. 1 Location: Unit ___ Section 27 Township 32 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 105 Intermediate 152 Casing 20 Bradenhead 42

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	152	20	0	20
10 min	0	152	20	0	20
15 min	0	152	20	0	20
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH slowly opened through 1/2" valve - cleared at 25 seconds. Nothing when opened after 5 min shut in. Int valve 1/2" opened slowly cleared at 1 min. - Long puff after 5 min shut in

By Sam Martinez

WSM
(Position)

Witness Monica Kuehling

E-mail address _____