



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 04 2016

Date of Test 5/4/2016 Operator Turner Production API #30-0 39-2311

Property Name Turner 26 Well No. 1 Location: Unit I Section 26 Township 26 Range 7

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 100 Intermediate — Casing 138 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>138</u>		
10 min	<u>0</u>	<u>—</u>	<u>138</u>		
15 min	<u>0</u>	<u>—</u>	<u>138</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Nothing on bradenhead

By Glenn R. Hise
Lease Operator
(Position)

Witness Paul Wicks

E-mail address glenn.hise@wqpit.com