



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4 MAY 2016 Operator CONDO/BURLINGTON API #30-0 39-25944

Property Name SAN JUAN 27-4 Well No. 49M Location: Unit E Section 30 Township 27 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 180 Intermediate Casing 179 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u> </u>	<u> </u>	<u>180</u>		
10 min	<u> </u>	<u> </u>	<u>181</u>		
15 min	<u> </u>	<u> </u>	<u>181</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By Rapnel Baldonado

Witness John Duran

MSO

(Position)

E-mail address

OIL CONS. DIV DIST. 3

MAY 04 2016