

OIL CONS. DIV DIST. 3

MAY 04 2016

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emr.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 4/14/2016 Operator San Juan Resources API #30-0 39-05649
Property Name Clark Well No. 5 Location: Unit E Section 6 Township 24N Range 3W
Pressure (Shut-In or Producing) Producing Tubing ## Intermediate NA Casing 131 Bradenhead 18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Table with columns: TIME, PRESSURES (BRADENHEAD, INTERMEDIATE, CASING), Flow Status (Steady Flow, Surges, Down to Nothing, Nothing, Gas, Gas & Water, Water), and BRADENHEAD/INTERMEDIATE FLOWED.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Blew down to 0 in 45 Sec, Through 2" valve. No vapor

Note: Repair 2" valve on Brandon Head 4/6/2016

By Terry Gwinn Lease Operator (Position) Witness