



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 10 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/10/2016 Operator Black Hills API #30-0 39-30278

Property Name Jicarilla 464 Well No. 724 Location: Unit H Section 30 Township 30 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 48 Intermediate 73 Casing 138 Bradenhead -4.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	73	139	0	138
10 min	0	73	139	0	138
15 min	0	73	139	0	139
20 min					
25 min					
30 min					

		FLOW CHARACTERISTICS	
		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing	X		X
Nothing			
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD -0.2 INTERMEDIATE 0.1

REMARKS:

BH had suction, down to nothing in 15 sec through 2" valve, Int. through 2" valve, Hard blow for 1 min 45 sec, Moderate blow for 30 sec, ~~to a tight~~ blew down to nothing in 3 min 10 sec.

By AB

Witness Jonathan Q. Kelly

(Position)

E-mail address _____