



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

http://emnr.state.nm.us/ocd/District III/district.htm

OIL CONS. DIV DIST. 3

MAY 10 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-10-16 Operator Burlington Res API #30-0 39-07082
Property Name San Juan 27-5 Well No. 57 Location: Unit 13 Section 13 Township 27 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 149 Intermediate 19 Casing 150 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	19	151	0	153
10 min	0	19	152	0	153
15 min	0	19	152	0	153
20 min				0	153
25 min				0	154
30 min				0	154

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓ Vapors
Surges		
Down to Nothing		
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH: Nothing when opened. Small puff when
opened after 5 min shut-in
gate valve on BH. Int-Med blow to really light at 5 min to

By Kevin Peterson

Witness Monica Kuehling Vapors at 8 min
10-15-20-25
30-

(Position)

E-mail address _____

Gas samples taken
Medium to light blow when opened after
5 min shut-in.