



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 22 2016

Date of Test 6-22-17 Operator Cherton API #30-0 39-06975
Property Name Enconita NP Well No. 137 Location: Unit 24 Section 24 Township 27 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate 0 Casing 16 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	16	0	16
10 min	0	0	16	0	16
15 min	0	0	16	0	16
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Successful completion 142 second tubing - BH - Nothing
when opened. Nothing when opened up for 5 min.
Shut in Int - Puff to dead at 2 seconds. Nothing

By Matthew

Witness Monica Kuebler
when opened after 5 min shut in

(Position)

E-mail address _____