

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (808) 334-8170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Tes	6-22-7	Operat	tor Red Wolf Production	MAPI #30-045-28906
Property Na	me E.L.	Well No	1 Location: Unit DS	Section 31 Township 25 Range 11
Well Status	(Shut-In or Proc	lucing) Initial PSI:	Tubing 27 Intermediate A	JA Casing 28 Bradenhead 2
OPEN BR	ADENHEAD A	ND INTERMEDIATI	E TO ATMOSPHERE INDIV	VIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BII Int Csg Int Csg			FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE	
TIME 5 min	NA 28		Steady Flow	
10 min	( 28		Surges	
15 min	/ 28		Down to Nothing	CIL CONS. DIV DIST. 3
20 min_			Nothing	JUN 2 2 2016
25 min_	1		Gas	
30 min_	1		Gas & Water	
			Water	
If bradenhead	flowed water, ch	eck all of the description	ons that apply below:	
CLEA	R FRESI	H SALTY	SULFUR BLACK	
DEMARKS.			ead Opsi. INTERM	BH after 5 min shut in.
ву Вило	Calluttur	<del></del>	Witness JKL	- NMOED
(Posit	ion)	9 e		
E-mail address				