

JUN 27 2016

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENTOIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://nemrds.state.nm.us/ocd/DistrictIII/3distric.htm>

## BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test May 20, 2016 Operator DJ Simmons API #30-0 39-23995

Property Name Lybrook Well No. 2 Location: Unit I Section 4 Township 23N Range 7W

Pressure (Shut-In or Producing) Shut In Tubing 6 Intermediate N/A Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

## PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE	
	BH	INT	CSG	INT	CSG
5 minutes	0		6		
10 minutes	0		6		
15 minutes	0		6		
20 minutes					
25 minutes					
30 minutes					

BRADENHEAD INTERMEDIATE

FLOWED

FLOWED

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas &amp; Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Well shut in, nothing on Bradenhead.

By Dustin K. Johnson Witness \_\_\_\_\_

Lease Operator

(Position)