



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

JUL 11 2016

(submit 1 copy to above address)

Date of Test 7-11-16 Operator Toddy Rod API #30-0 39-24143
Property Name Chacon Apache Well No. 11 Location: Unit 14 Section 14 Township 23 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 2 Intermediate 0 Casing 2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	3	0	3
10 min	0	0	3	0	3
15 min	0	0	3	0	3
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>Vacuum</u>	<u>Vacuum</u>
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Outside BH inside Int - BH Vacuum
When opened nothing when opened after 5 min shut in
picture have been taken of valves below gr.

By Tim

Witness Monica Cuckling

(Position)

E-mail address _____

Int. Vacuum when opened at
10 seconds. Nothing when
opened after 5 min shut in