



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III/3district.htm](http://emrdd.state.nm.us/ocd/District%20III/3district.htm)

JUL 26 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-22-2016 Operator SCHALK DEVELOPMENT API #30-0 39-20594

Property Name SCHALK 52 Well No. 1 Location: Unit m Section 24 Township 29N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 129 Intermediate — Casing 161 Bradenhead 120

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	40		164		
10 min	35		165		
15 min	35		166	N	A
20 min	20		169		
25 min	15		170		
30 min	8		171		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	XX	
Surges		
Down to Nothing		
Nothing		N A
Gas	XX	
Gas & Water		
Water		

(Time Cycle had just shut in.)

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 68 INTERMEDIATE —

REMARKS:

** WELL WENT TO SHUT IN CYCLE 3 min BEFORE TEST - MONITORED TOG 129-134 in 30 min*

OPENED BH - HARD LONG BLOW - 5 min BLOWED DOWN SOME BUT STILL STEADY - 10 min STILL

STEADY FLOW - 15 min LIGHTER BLOW BUT STILL STEADY - 20 min SAME - 25 min SAME - 30 min LIKE STEADY FLOW

By SCOTT ROBERTS

Witness —

Field Tech

(Position)

E-mail address —