



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-15-16 Operator Burlington API #30-0 39-23501
Property Name SS30644 SW Well No. 1124 Location: Unit 26 Section 30 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 268 Intermediate 0 Casing 14 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	0	14	0	14
10 min	0	0	14	0	14
15 min	0	0	14	0	14
20 min				0	15
25 min				0	15
30 min				0	15

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		<u>1 vapor</u>
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH Nothing when opened. Nothing
when opened after 5 min shut in. Int. Med.
to high flow at 2 min. Vapors at 2.5 min - 5 min - 10

By Billy Smith

Witness

Norica Fuchling

SWD M 50

(Position)

Vapors 15-20-25-30 more vapors
after 5 min shut in

E-mail address _____