NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

JUN 30 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/25/2016 Operator Burlington Resources API # 3003925930

Property Name SAN JUAN 27-5 UNIT Well No. 107M Location: Unit P Section 13 Township 027N Range 005W

Well Status Flowing Initial PSI: Tubing 144 Intermediate 0 Casing 146 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	BRADENHEAD BH	BRADENHEAD Int	BRADENHEAD Csg	INTERM Int	INTERM Csg
5 min		0	148		152
10 min		0	149		152
15 min		0	150		153
20 min		0	150		
25 min		0	151		
30 min		0	151		

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow	Y	
Surges		
Down to Nothing		
Nothing		Y
Gas		
Gas & Water		
Water	Y	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR Y FRESH SALTY SULFUR BLACK

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE Bradenhead 0 Intermediate 0

REMARKS:

BH- Flowing water, no gas. Made a total of about 1-1/3 gallons of water during the entire 30 min. BH test thru 1" valve. Water samples have been collected. INT- Nothing thru 1" valve. Met BH test criteria, no witness needed.

Tested By kevinp Witness