NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

RCVD JUL 25 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-25-12 Operator Burlington Res API #30-0 45-07284

Property Name Florance C Well No. 2A Location: Unit ___ Section 20 Township 28 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 132 Intermediate 36 Casing 137 Bradenhead 25

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	37	135	0	128
10 min	0	36	132	0	131
15 min		36	130	0	133
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		- Vapors
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 6 INTERMEDIATE 0

REMARKS: BH Blew to nothing in 5 seconds - Well came on just 10 minutes
Int. Hard Blow just 30 seconds to light in 1 min 32 sec. Vapors at 5 min 10 - 15.

By J. D. M. Witness Monica Kuehling

MSO - CCPC
(Position)

E-mail address _____