

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

> RCVD JUL 25'12 OIL CONS. DIV.

BRADENHEAD TEST REPORT

DIST. 3

(submit 1 copy to above address)	
Date of Test 7-25-12 Operator	or Bulington Cos. API #30-045-27292
Property Name Shay Well No. 800 Location: Unit Section/8 Township 8 Range 8	
Well Status(Shut-In or Producing) Initial PSI: Tubing 1 Intermediate A Casing Bradenhead 6	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 34	Steady Flow
10 min 0 33	Surges
15 min 0 33	Down to Nothing
20 min	Nothing
25 min	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS: down to nothing in 3 Deconds.	
By J.DOM Witness / Ouca Kriehlung	
MSO - COPC (Position)	
E-mail address	