



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2 AUG 2016 Operator BURLINGTON API #30-0 39-22 T2 7

Property Name SAN JUAN 305 Well No. 76 Location: Unit A Section 15 Township 30 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 143 Intermediate 0 Casing 150 Bradenhead 7.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	150	0	150
10 min	0	0	160	0	150
15 min	0	0	175	0	150
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW DOWN TO
NOTHING IN 2 MINUTES. OPENED THE INTERMEDIATE AND
NOTHING CAME OUT.

By Danell Bunker

Witness John Bunker

(Position)

E-mail address _____