



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 01 2016

Date of Test 8-1-16 Operator Burlington Kes API #30-0 45-13189

Property Name Allison Well No. 73X Location: Unit 19 Section 19 Township 32 Range 6

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 123 Intermediate 94 Casing 129 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	130	0	126
10 min	0	0	131	0	124
15 min	0	0	132	0	122
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Puff when opened - Nothing when opened after 5 min shut-in. Int - dead at 9 seconds. Plugger came up during test. Nothing when opened.

By [Signature]

Witness

Monica Kuehling
after 5 min shut-in

(Position)

E-mail address _____