



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 03 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-3-16 Operator Burlington API #30-0 45-2514
Property Name Culpeper Martin Well No. 1F Location: Unit 31 Section 31 Township 32 Range 12
Well Status(Shut-In or Producing) Initial PSI: Tubing 63 Intermediate 64 Casing 65 Bradenhead 128

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>3</u>		<u>66</u>			Steady Flow <u>✓</u>	
10 min	<u>3</u>		<u>66</u>			Surges	
15 min	<u>2</u>		<u>67</u>			Down to Nothing	
20 min	<u>2</u>		<u>67</u>			Nothing	
25 min	<u>1</u>		<u>67</u>			Gas <u>✓</u>	
30 min	<u>1</u>		<u>68</u>			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH ✓ SALTY ✓ SULFUR ✓ BLACK ✓

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 19

INTERMEDIATE ✓

REMARKS:

Med hard blow just 15 seconds to med to light at 5
for rest of 30 minute test
Pond next to site

By Tim Ferguson

Witness Mona Kuehling

MSO Conita Phillips
(Position)

Gas analysis

E-mail address _____