NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

OIL CONS. DIV DIST. 3

AUG 01 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-1-16 Operator Burlington Res API #30-0 45-27366

Property Name Allison Ut. Well No. 113 Location: Unit ___ Section 19 Township 32 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 1 Intermediate N/A Casing 3 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		3		
10 min	0		3		
15 min	0		2.9		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Whisper to blead at 2 seconds through 1/4" valve. Nothing when opened after 5 Min Shut in

By [signature] Witness Monica Kuehling

(Position)

E-mail address _____