



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

DEC 02 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-30-15 Operator COPC API #30-0 39-26367

Property Name 30-5 Well No. 48M Location: Unit 20 Section 20 Township 30 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 137 Intermediate 7 Casing 137 Bradenhead 47

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0	7	137	0	140
10 min	0	7	138	0	141
15 min	0	7	138	0	141
20 min	0	7	139		
25 min	0	7	139		
30 min	0	7	139		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow ☒	
Surges	
Down to Nothing	☒
Nothing	
Gas ☒	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1 INTERMEDIATE 0

REMARKS:

BH blew down to vapors 5 min test - vapor 10 min test - vapor
15 min test - vapor 20 min test - vapor 25 min test - vapor 30 min test - vapor
Inter blew down to dead in 20 sec.

By Daniel Renteria

Witness J. K. H. NMOC

(Position)

E-mail address _____