



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DEC 18 2015

Date of Test 12-5-15 Operator ENERVEST OPERATING API #30-0 45341620000

Property Name NAVAJO 11 Well No. 7 Location: Unit G Section 11 Township 25N Range 10W

Well Status(Shut-In or Producing) Initial PSI: Tubing 96 Intermediate MA Casing 100 Bradenhead B

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	<u>7</u>	<u>MA</u>	<u>100</u>		
10 min	<u>0</u>	<u>MA</u>	<u>100</u>		
15 min	<u>0</u>	<u>MA</u>	<u>100</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 7

INTERMEDIATE MA

REMARKS:

braden head blew down

By Saxon Chenover

Witness _____

operator

(Position)

E-mail address schenover@enervest.net