



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

AUG 16 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-16-16 Operator Burlington API #30-0 4529809
Property Name Allison Well No. 6m Location: Unit 16 Section 32 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 217 Intermediate 0 Casing 215 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	215	0	216
10 min	0	0	215	0	216
15 min	0	0	215	0	216
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>Vacuum</u>
Nothing	<u>—</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

At Vacuum when opened - Nothing when opened
after 5 min shut in Nothing when opened after
5 min shut in

By Brian H. Smith

Witness Momca Kuchling

(Position)

E-mail address —