



[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3
AUG 22 2016

(submit 1 copy to above address)

(submit 1 copy to above address)

Date of Test 8-22-16 Operator Merron O'G API #30-0 39231-83

Property Name Canada Mesa Com Well No. 4 Location: Unit 10 Section 24 Township 6

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 180 Intermediate 174 Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		200		
10 min	0		200		
15 min	0		200		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

REMARKS: Nothing when opened. - poured water down bottom pipe to see if valve open. It is open - Nothing when opened after 5 min. Shut in.

By Frank Hanna
Pumper
(Position)

Witness W Jones & Co

E-mail address _____