



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3
SEP 12 2016

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrdr.state.nm.us/ocd/District III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-12-16 Operator Southland Royalties API #30-0 39-25384
Property Name Cimacusa 4 103 Well No. 15 Location: Unit 0 Section 10 Township 32 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 743 Intermediate Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>4</u>		
10 min	<u>0</u>		<u>4</u>		
15 min	<u>0</u>		<u>4</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow
Surges
Down to Nothing
Nothipg
Gas
Gas & Water
Water

f bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE

REMARKS:

Nothing when opened. Nothing when
opened after 5 min shut in

William D. Samson
Field Foreman
(Position)

Witness

Monica Steckling

mail address wsemler@CT Field Svcs.com