



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrwd.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-22-2016 Operator SCHALK DEVELOPMENT API #30-0 39-20579
Property Name SCHALK 54 Well No. 1 Location: Unit H Section 2 Township 30N Range 5W
Well Status (Shut-In or Producing) Initial PSI: Tubing 218 Intermediate Ø Casing 382 Bradenhead 46

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	Ø	Ø	387	Ø	388
10 min	Ø	Ø	387	Ø	388
15 min	Ø	Ø	387	Ø	388
20 min	Ø	Ø	387	Ø	389
25 min	Ø	Ø	388	Ø	389
30 min	Ø	Ø	388	Ø	389

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	XX
Nothing	XX
Gas	XX
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE Ø

REMARKS:

RE-TEST FROM 6-13-2016 - WAS DISCOVERED THIS WELL DOES HAVE AN
INTERMEDIATE STRING. DUG OUT INTERM VALVE & PLUMBED TO SURFACE. OPENED
BH - SHORT SOFT PUFF DOWN TO NOTHING - NOTHING ON INTERM - PULLED GAS SAMPLES CSG + BH ON INTERM ^{NO PRESS}

By SCOTT RODRIGUES

Witness _____

FIELD TECH

(Position)

E-mail address _____